

信毅輪船沉船

日期：2012/06/07

地點：台灣新竹近海

項目名稱：信毅輪船沉船影像檢查項目

目的：沉船檢查，水下攝影，檢查是否漏油，並回報高雄港務局

工作深度：水深 70 公尺

NOTICE TO MARINERS

Published by Naval Meteorological & Oceanographic Office, Taiwan Waters – Cargo Ship Sank

Positions - (A)Lat.24°50'13.0"N., Long.120°30'07.0"E. (WGS84)

(B)Lat.22°59'18.0"N., Long.118°48'48.0"E. (WGS84)

(A)Lat.24°50'19.2"N., Long.120°29'37.5"E. (GRS67)

(B)Lat.22°59'24.1"N., Long.118°48'19.0"E. (GRS67)

Details - Two Panama cargo ships, "XIN YI" and "DLII STAR", separately sank at the above position (A) & (B) on October 19, 2010. Mariners are advised to navigate with caution in the area.



信毅輪船沉船照



船裡管路是否漏油



檢查船底是否有裂痕



檢查船底是否有裂痕

Youtube

<http://www.youtube.com/watch?v=r78WTb3plzQ>